



FRONT VIEW




BOOTH# HALL COLUMN

RIGGING PLAN SCALE:1/4"=1'-0"





ENTRANCE




HANGING SIGN FRAME (QTY. 2)

(90LBS TOTAL)

HANGING SIGN SETUP INSTRUCTIONS

- 1. REMOVE ALL ITEMS FORM PACKAGING ONTO A CLEAN AREA. LAY OUT TUBE ACCORDING TO DIAGRAM.
- 2. ASSEMBLE ALL BUNGEE-CORDED TUBES. ROTATE UNTIL SPRING LOCK SNAPS INTO PLACE.
- 3. ALIGN MATCHING LABELS TO ONE ANOTHER ROTATE TUBES UNTIL SPRING LOCK SNAP IN PLACE.
- 4. WEARING THE GLOVES PROVIDED. SLIDE THE FABRIC PILLOWCASE OVER EACH FRAME STARTING ALONG THE BASE.
- 5. ALIGN THE GRAPHIC SO THE EYEBOLTS ARE ACCESSIBLE THROUGH THE SEWN HOLES IN THE FABRIC. ZIP CLOSED ALONG THE TOP.
- 6. ATTACH HANGING HARNESS TO EYEBOLTS ON TOP FRAME. RAISE FRAME SLIGHTLY ABOVE GROUND.
- 7. ATTACH BOTTOM FRAME TO TOP FRAME USING SMALL CABLES AS SHOWN IN DIAGRAM. CAREFULLY RAISE FRAME INTO DESIRED LOCATION.

BOOTH#1838



BOOTH# 1932/ 1835

SET UP INSTRUCTIONS:

1. LAY OUT MAIN ELECTRICAL AS SHOWN -



3. INSTALL CARPET AND PAD AS NEEDED.

ELECTRICAL REQ'MTS







(2) @ 10A (4) @ 20A















BOOTH#1838 - 20' BOOTH -HANGING SIGN 2" -BOOTH# 1932/ 1835 **★** BOOTH# 1944/ 1845 HANGING— SIGN — HANGING SIGN 1A _ 3'-2" -— 1'-11" → — HANGING SIGN "6 ⁴ ENTRANCE BOOTH# HALL COLUMN FLOOR PLAN SCALE:1/2"=1'-0"










ROLLING DISPLAY (QTY 2)



TYPICAL GRAPHIC WITH CABLES

